


UPGRADE CHIP FOR FA-1000 REV.8 BOARD

Upgrades should only be done by a trained technicians. Always use the proper IC extraction tools. Failure to meet these conditions could void the warranty.

1. Check for MD-514A Main Board Revision – Rev.K or lower, do not proceed if otherwise.
2. Locate and remove IC – U22
3. Insert the upgrade IC and check for IC Orientation – as per Picture
4. Check panel configuration.



U22 Location

Orientation

Canada

25 Interchange Way
Vaughan, ON L4K 5W3
Tel: (888) 660-4655
(905) 660-4655
Fax: (905) 660-4113

U.S.A

4575 Witmer Industries
Niagara Falls, NY 14305
Tel: (888) 660-4655
(905) 660-4655
Fax: (905) 660-4113



www.mircom.com

LT-1070 Rev. 1