

UPGRADE CHIP FOR FA-1000 REV.9 BOARD

Upgrades should only be done by a trained technicians. Always use the proper IC extraction tools. Failure to meet these conditions could void the warranty.



IDENTIFYING REV.9 BOARD

1. Check for MD-514A Main Board Revision - Rev. L, M, OR N, do not proceed if otherwise
2. Check for "UL 864 REV 9 CERTIFIED" Label

REPLACING UPGRADE CHIP

3. Insert the upgrade IC [SF-119] and check for IC orientation - as per Picture
4. Check panel configuration

Note: SF-119 is the catalog number for upgrade chip for Rev.9 board



Canada
25 Interchange Way
Vaughan, ON L4K 5W3
Tel: (888) 660-4655
(905) 660-4655
Fax: (905) 660-4113

U.S.A
4575 Witmer Industries
Niagara Falls, NY 14305
Tel: (888) 660-4655
(905) 660-4655
Fax: (905) 660-4113



www.mircom.com

LT-1081 Rev. 1