

FleXNet/MMX

Version 12.1.39 Release Document & Firmware Update Recommendations

As of APRIL 2, 2019 production of the FlexNet product line and components will begin with FleXNet firmware, V12.1.39. This change is to ensure the most current updates and enhancements are provided to new and existing systems. Ideally, this update is intended for **new system installations** where final testing and verification has not yet been completed. For existing systems, the following recommendations should be considered if upgrading.

Existing systems operating older versions **are not required** to update to this version unless additional features are needed or required. For component replacement or servicing of existing systems, components contain newer software should be downgraded to match the existing system software. Access to older software versions is provided by contacting Mircom Applications Group at ApplicationGP@mircomgroup.com

This update is intended for systems currently operating older V12.1.XX FlexNet series software ONLY.

This update is intended for systems currently operating with V12.1.9 software (or newer) since the software changes can be properly assessed and appropriate retesting/verification can be completed in accordance to local governing standards and codes.

This update is not recommended for systems currently operating older FlexNet series software such as v10 and v11.

Update Enhancements

Major Enhancements:

- Improved Signal Silence Inhibit for Water Flow Alarms
- S.A. Flag Implementation for Supervisory/Monitor Input Zones
- Analog Telephone/Paging Bus supervision
- Updated Ground Fault Reporting
- Expanded Internal Logic limits
- Expanded the Advanced Logic Editor to include HOA manual switches and output modules

Minor Enhancements:

- Added disable Waterflow Retard feature
- Added water Flow Alarm Zone
- Added silence Audible Only feature
- Single Trouble Bypass feature
- Manual Control switch limit per system increase
- AP polling sequence & SLC initialization process
- OpenGN control for large campus applications
- Addressable Sounder Base internal sync
- AP Broadcast Command
- Get Job feature
- Built-in manufacturer sync protocol
- Web Services feature

For the latest Mircom Technical Bulletins & Product Updates

<https://mircom.com/technical-support/technical-bulletins/>

Register an account with Mircom.com to access the technical documents for V12.1.39

<https://mircom.com/technical-support/documents-firmware-software-downloads/>

For Technical Support Please Contact Us at:

Email:

TechSupport@mircom.com

OR

Telephone:

1-888-MIRCOM5 (1-888-647-2665)

Mircom strives to offer the highest quality products and services, on occasion an issue may require field action and we regret when these issues arise. As part of our commitment to quality we incorporate any findings into a continuous improvement process so as to better serve our customers in the future. As part of our support offering please feel free to contact us with any inquiries or assistance you may require.

We Want Your Feedback ...

We are always looking for your feedback on our Products and Solutions.

- Suggestions, Ideas, Needs, Problems
- Project Wins & Losses
- Case Studies & Installation Photos
- Sales & Marketing Tools
- Anything else that help our business grow together

If you have anything to share, please contact us directly at:

productmanagement@mircomgroup.com

Regards,

Lisa Turner

Sr. Product Manager Fire Products

Mircom Group of Companies

25 Interchange Way, Vaughan, Ontario, Canada, L4K 5W3

T: 905.660.4655 ext . 3100 | 1.888.660.4655

E: lturner@mircomgroup.com