

## Note to Customer:

The factory configuration for the main MD-764 is configured to accommodate the MD-1007 display ONLY.

If the old MD-644 display is to be accommodated the MD-764 must be reconfigured.

This can be performed through the software configurator.